


Attachment to Oct. 2, 1998 I&E of Surface Management notice (serial no. UTU 66358) -- Photographs. The location, number, and direction of photos is shown on the map attached.

Photo 1 is a (wide angle) view to the SSE - filled drainage is in mid-photo (blue arrows), highwall cut in eastern part of project area is at left center (green arrow, see vehicle for scale), area from highwall to right center-edge of photo is the project area; there is some miscellaneous pieces of equipment left on location (at right - black arrow).

Photo 2 is a (wide angle) view to the west (from atop the highwall in photo 1) - stockpiles assumed to be top soil are at left (black arrow), old settling pond is at right (blue arrow), and road to Green River bank is at right (green arrow).



Sec. 6

R23E
R24E

9/04/7/050

9/04/7/050

Oct 21 1998 66358
14E 1N06E 01
P4070V

Green River

east bank

existing
access road

entry road

Intermittent drainage


Sno-Ben #2
project area

cobble material for
drainage (for road)

Pebble Puppy 2
66358
project area

highwall

settling pond dam



base map produced
4/13/90

N